

Release Note

Product Name	<ST3402>
Release Version	<Vivotek 2.0.0.21, English>
Date	<2006/09/29>

System Requirements

<Software>	< Windows 2000/XP >
<Software>	< DirectX8.0 (When in windows 2000) >

Features/Bugs fixed

a	In Playback, StepForward mode can't retrieve all packets
b	In Playback, some channels can't run in StepForward mode (the button is disabled)
c	In Playback, the button status is incorrect when switch a paused channel to un-paused channel.
d	Recording will be stopped and do not restarted, when user change frame size by IE.
e	Manual recording will not be stopped when user asks for scheduler recording and there is no recording action in current time.
f	Playback will crash when transducer AVI.